



GSM SERVICE SUPPORT GROUP	2004.01.22
Level 3 Board Layout	Rev. 1.0
V300 V400 V500 V600	8488258N03 D1
Alexander Buehler, Michael Hansen	Page 1 of 2

